



TATA POWER-DDL

TPDDL/REGULATORY/2025-26/03/ 410
Jan 12, 2026

Office of the Head (Regulatory)

The Secretary

Delhi Electricity Regulatory Commission
Viniyamak Bhawan, C-Block, Shivalik
Malviya Nagar, New Delhi-110017

Subject: Submission of details of electrical accidents and action taken in line with DERC (Compensation to Victims of Electrical Accidents) Regulations, 2024 for the month of Dec 2025.

Dear Sir,

The Hon'ble Commission had notified the DERC (Compensation to Victims of Electrical Accidents) Regulations, 2024 which was published in the official gazette on 26.07.2024. With their publication in the official gazette, these Regulations have come into force from 26.07.2024 as provided in these Regulations.

Further, these Regulations provide for submission to the Hon'ble Commission by 15th of every succeeding month, the details of electrical accidents occurring within the respective jurisdiction of the distribution licensee and action taken thereon in accordance with these Regulations. Same is reproduced below for ready reference:

"18. Information to the Commission: -

The generating company or transmission licensee or distribution licensee shall submit to the Commission by 15th of every succeeding month, the details of electrical accidents occurring within their respective jurisdiction and action taken thereon in accordance with these Regulations."

Accordingly, Tata Power-DDL is submitting the report, enclosed herewith as **Annexure-1**, for the month of Dec 2025 i.e. 01.12.2025 to 31.12.2025.

We hope the Hon'ble Commission would find the above in order.

Yours Sincerely,
For Tata Power Delhi Distribution Ltd.

Ritu Gupta
Head (Regulatory)

Annexure-1

S No.	Date of Incident	Zone/ District	Address/ Location	Brief Detail	TPDDL network involved?	Fatal/ non-fatal	Remarks
1	25.12.2025	Zone 513/ Kirari	TPDDL Double Pole Transformer (fenced) located in Karala Agricultural Area near Sultanpur Road (HT513-17/21/14DA/9)	At around 14:27 Hrs, the zonal team received an information from the Tata Power-DDL Security Control Room regarding an unknown person found in unconscious condition inside a 25 KVA pole-mounted Distribution Transformer substation located at Karala Agricultural area near Sultanpur Road (HT513-17/21/14DA/9). Upon receipt of information, Tata Power-DDL zonal team immediately reached at site at around 14:35 Hrs. After reaching at the site, zonal team observed that the Delhi Police officials and one public person Mr. Satish Mathur (Mob: 9873601456) were present at the site. Thereafter, official of Delhi Police asked us to check the current leakage, if any, and test was conducted accordingly in their presence using a neon tester, however no leakage was detected on the fencing. Subsequently police official present at the site instructed zonal team to switch off the DT supply to allow entry/access inside the substation for further checking by them. Accordingly, PTW No. 43228-M was availed at 15:01 hrs, and after securing proper safety zone at the site, the police team entered inside the substation. After carrying out thorough checking, Delhi Police team removed the unidentified person from the said location and also collected requisite evidences from the spot. Thereafter, PTW was closed at 17:08 Hrs. It was observed that the DT was properly fenced, earthed and having danger plates installed as per CEA Safety Regulations 2023. However, zonal team also observed that lock installed on the fencing was found damaged and removed from its place and was lying near the fencing.	No	Fatal	The Electrical Inspector has been informed and the enquiry report is awaited.