



TATA POWER-DDL

TPDDL/REGULATORY/2026-27/03/ 115
June 11, 2026

Office of the Head (Regulatory)

The Secretary
Delhi Electricity Regulatory Commission
Viniyamak Bhawan, C-Block, Shivalik
Malviya Nagar, New Delhi-110017

Subject: Submission of details of electrical accidents and action taken in line with DERC (Compensation to Victims of Electrical Accidents) Regulations, 2024 for the month of May 2026.

Dear Sir,

The Hon'ble Commission had notified the DERC (Compensation to Victims of Electrical Accidents) Regulations, 2024 which was published in the official gazette on 26.07.2024. With their publication in the official gazette, these Regulations have come into force from 26.07.2024 as provided in these Regulations.

Further, these Regulations provide for submission to the Hon'ble Commission by 15th of every succeeding month, the details of electrical accidents occurring within the respective jurisdiction of the distribution licensee and action taken thereon in accordance with these Regulations. Same is reproduced below for ready reference:

"18. Information to the Commission: -

The generating company or transmission licensee or distribution licensee shall submit to the Commission by 15th of every succeeding month, the details of electrical accidents occurring within their respective jurisdiction and action taken thereon in accordance with these Regulations."

Accordingly, Tata Power-DDL is submitting the report, enclosed herewith as **Annexure-1**, for the month of May 2026 i.e. 01.05.2026 to 31.05.2026.

We hope the Hon'ble Commission would find the above in order.

Yours Sincerely,
For **Tata Power Delhi Distribution Ltd.**

Ritu Gupta
Head (Regulatory)

Encl: As mentioned above

Annexure-1

S No.	Date of Incident	Zone/ District	Address/ Location	Brief Detail	TPDDL network involved?	Fatal/ non-fatal	Remarks
1	01-05-2026	Zone - 502	A block Bunkar colony, Near house no- 404, Zone - 502	<p>On dated 01-05-2026 at 21:41, Tree branch fallen and street light iron pole tilted complaint received from PCR call, immediately on-duty ZSO along with the team promptly reached the site. Upon inspection, it was observed that a tree branch had fallen on the LT ABC line. Due to the impact/jerk on the LT cable, the nearby streetlight iron pole was also found tilted. Accordingly, LT ESD permit was availed by team for removing tree branch and supporting tilted iron pole, while after clearing the network by removing the tree branch. Team started the work to provide the support to tilted streetlight pole by tying with GI wire, therefore LM (Mr. Ajay Pratap) placed the ladder on boundary wall for tying GI wire on Steel railing, where he got disbalanced and fell on the ground.</p> <p>As a result of incident injury occurred on his left hand and back portion, victim was immediately rushed to Deep Bandhu Hospital for primary treatment and later referred to Vinayak hospital for further treatment. Currently, the victim is in stable condition.</p> <p>Medical observation: - Fractured on left hand b/w wrist & elbow.</p>	Yes	Non-Fatal	NA
2	22-05-2026	Zone - 571+581	E-2/7 Substation, Naharpur	<p>Electrical Flash occurred, while creating of safety zone on 400AMP LT ACB of DT -1 at E-2/7/ S/Stn.</p> <p>Foreman was initially taken to BR Ambedkar Hospital Rohini and then referred to Safdarjung hospital, Burn Casuality Ward for further treatment.</p>	Yes	Non-fatal	The enquiry report from the Electrical Inspector is awaited.

